

Check all bolts and nuts for tightness. Correct any conditions that could cause destructive vibration or leakage

5/16

5051

316L

316L

316L

316L

5051



**EASTERN**<sup>®</sup>  
CENTRICHEM<sup>®</sup> PUMP  
MODEL NO.  
ECJ3-ASACCNSS  
SERIAL NO.  
AD997529-2  
**PULSAFEEDER**<sup>®</sup> **IMEX**  
ENGINEERED PRODUCTS FLUID & METERING

