


انجمن محترم سازندگان تجهیزات صنعتی ایران
با سلام

به استحضار می‌رساند این شرکت طی دو فقره پیش فاکتور با شماره های FHUB-2024-029 Moulds مورخ 2024/02/02 شامل قالب های بدنه سازی خودرو کاپرا جدید (U&B) و همچنین پیش فاکتور شماره jzigs FHUB-2024-029 مورخ 2024/02/02 شامل فیکسچرهای مجموعه سازی خودرو کاپرا (U&B) ، به جهت افزایش عمق ساخت داخل محصولات تولیدی خود اقدام به واردات تجهیزات مورد نظر نموده است. از آنجائیکه این تجهیزات مشمول استعلام ساخت داخل می‌باشند و در این خصوص نامه با شماره 2708677 مورخ 1403/02/23 توسط سازمان صمت استان تهران به آن انجمن محترم ارسال شده است خواهشمند است بررسی و اعلام نظر نمایید.

لازم به ذکر است با توجه به اینکه این نامه استعلام شامل دو فقره پیش فاکتور می‌باشد یک فقره پیش فاکتور در قسمت (پیوست مشخصات فنی تجهیز) و تصویر یک فقره دیگر به همراه توضیحات فوق در قسمت (پیوست کاتالوگ) در سامانه آپلود گردید. با توجه به اینکه حجم کاتالوگ زیاد بوده و امکان آپلود در سامانه وجود ندارد فلذا CD کاتالوگ توسط نماینده این شرکت بصورت حضوری خدمتتان ارسال می‌گردد.

با تشکر




Mohsen yousefnejad
Foreign Purchasing Dept.
Expert
Tel: +98 21 48 09 7325
Fax: +98 21 44 90 85 01
Mobile: +98 919 795 22 95
Email: m.yousefnejad@bahman.ir

Bahman Group (Public)
No. 279, 13TH km of Lashgari Hwy
Tehran 13999-39711, Iran
www.bahman.ir

ANQING FLEXHUB INTERNATIONAL IMPORT & EXPORT CO., LTD

PROFORMA INVOICE

Seller(Name,Address) ANQING FLEXHUB INTERNATIONAL IMPORT & EXPORT CO., LTD. ADD: NO.308, 3RD FLOOR, COMPREHENSIVE OFFICE BUILDING, ANQING COMPREHENSIVE BONDED ZONE, HUANCHENG EAST ROAD, JINGKAI DISTRICT, ANQING, ANHUI, CHINA TEL:0086 1860962660						Proforma Invoice Number: FHUB-2024-029 Jigs Proforma Invoice Date: 2024/02/02 Proforma Invoice Valid Until: 2026/02/02 Buyer Reference Seller's Reference					
Consignee(Name,Address): Bahman Motor Company Address:No 279, 13th km of Karaj Makhsos Rd., Tehran, 1399939711.IRAN Tel: +98 21 48097 717 Fax:+98 21 48097 203 Commercial ID : 10102384652						Buyer (Name,Address) : Bahman Motor Company Address:No 279, 13th km of Karaj Makhsos Rd., Tehran, 1399939711.IRAN Tel: +98 21 48097 717 Fax:+98 21 48097 203 Commercial ID : 10102384652					
Freight Forwarder (Name, Address):						Country of Beneficiary: China Country of Origin Country of Destination China Iran					
Partial Shipment: () Not allowed (✓) Allowed			Transshipment: () Not allowed (✓) Allowed Through UAE Ports			Terms of Delivery FOB		Relevant Location Shahid Rajaei / Shahid Bahonar Port - Bandar Abbas-Qeshm Persian Gulf-Iran			
Transport Mode and Means By Sea			Port/Airport of Loading Any China Por			Terms of Payment 100%TT in advance		Transaction Currency Euro			
Port/Airport of discharge			Final Place Delivery			Total Gross Weight 60568.9		Total Net Weight 60568.9			
Shipping Marks; Transport Unit ID			No. and kind of packages shipping description of goods			Shahid Rajaei / Shahid Bahonar Port - Bandar Abbas-Qeshm Persian Gulf-Iran Shahid Rajaei / Shahid Bahonar Port - Bandar Abbas-Qeshm Persian Gulf-Iran			60568.9 60568.9		
Item	HS CODE	PRODUCTION YEAR	Description	QTY (pcs)	NW	G/W	Unit Price (Euro)	Amount (Euro)			
1	84798990	2022	Tooling jigs for body parts of Capra(U&B)	91	46954.00	46954.00	17006.44	1547586.040000			
2	84798990	2022	Tooling jigs for body parts of Capra(U&B)	73	13614.90	13614.90	6197.45	452413.850000			
TOTAL				164	60568.90	60568.90		1999999.890			
Manufacturer :ANQING FLEXHUB INTERNATIONAL IMPORT & EXPORT CO., LTD.						Total FOB amount :					
BANK ACCOUNT DETAILS: Beneficiary: ANQING FLEXHUB INTERNATIONAL IMPORT AND EXPORT CO., LTD. NO.308, 3RD FLOOR, COMPREHENSIVE OFFICE BUILDING, ANQING COMPREHENSIVE BONDED ZONE,HUANCHENG EAST ROAD, JINGKAI DISTRICT, ANQING, ANHUI, CHINA Beneficiary's A/C No: 225013420461000013(EUR) Beneficiary's Bank: HUIZHANG BANK CORPORATION LTD Bank's ADD: NO.528 RENMIN ROAD ANQING ANHUI CHINA Swift/BIC: HFCBCNSH						Discount		Freight Charges (Euro)		TOTAL AMOUNT : EUR 1,999,999.89	
It is hereby certified that this invoice shows the actual price of the goods described, that no other invoice has been or will be issued, and that all particulars are true and correct.						NAME OF SIGNATORY  SEAL AND SIGNATURE					

ANQING FLEXHUB INTERNATIONAL IMPORT & EXPORT CO., LTD

ROW	part no	part name	QTY	unit price	total price	total net	total gross
1	BQ1023-03-001	Left headlamp panel sub assembly fixture (large water tank)	1	4000	4000	122	122
2	BQ1023-03-002	Right headlamp panel sub assembly fixture (large water tank)	1	4000	4000	122	122
3	BQ1023-03-003	Left headlight panel assembly fixture (large water tank)	1	4400	4400	132	132
4	BQ1023-03-004	Right headlight panel assembly fixture (large water tank)	1	4400	4400	132	132
5	BQ1023-03-007	Left headlight panel assembly fixture (small tank /VM)	1	4000	4000	120	120
6	BQ1023-03-008	Right headlight panel assembly fixture (small tank /VM)	1	4000	4000	120	120
7	BQ1023-03-009	Left headlamp panel sub assembly fixture (VM)	1	1650	1650	50	50
8	BQ1023-03-010	Right headlamp panel sub assembly fixture (VM)	1	1650	1650	50	50
9	BQ1023-03-011	Mounting bracket Assembly (G3)	1	1650	1650	50	50
10	BQ1023-03-012	Mounting bracket assembly for left and right sub-boards	1	1650	1650	50	50
11	BQ1023-03-013	Left front wheel cover sub assembly fixture	1	3600	3600	110	110
12	BQ1023-03-014	Right front wheel cover sub assembly fixture	1	3600	3600	110	110
13	BQ1023-03-015	Left front wheel cover assembly jig	1	3300	3300	100	100
14	BQ1023-03-016	Right front wheel cover assembly jig	1	3300	3300	100	100
15	BQ1023-03-023	Front coaming sub assembly fixture	1	8200	8200	250	250
16	BQ1023-03-024	Front coaming assembly fixture	1	8200	8200	250	250
17	BQ1023-03-029	Headlamp Assembly fixture (VM)	1	3300	3300	100	100
18	BQ1023-03-030	Headlamp assembly fixture (large water tank)	1	3600	3600	110	110
19	BQ1023-03-031	Clamp for radiator lower beam assembly	1	1650	1650	50	50
20	BQ1023-03-032	Cooler Lower Beam Assembly Fixture (VM)	1	2000	2000	60	60
21	BQ1023-03-033	Heat sink lower beam screw positioning welding jig	1	1300	1300	40	40
22	XZSC001	Heat sink lower beam screw positioning welding jig E7	1	66	66	2	2
23	BQ1023-03-034	Radiator upper beam Assembly (Small water tank /VM)	1	2600	2600	80	80
24	BQ1023-03-035	Upper beam assembly radiator (large water tank)	1	3000	3000	90	90
25	BQ1023-03-038	Clamp for lower beam of radiator left stiffener plate assembly (homemade)	1	660	660	20	20
26	BQ1023-03-039	Clamp for right stiffener plate assembly of lower beam of radiator (homemade)	1	660	660	20	20
27	BQ1023-03-040	Cooler lower beam left stiffener assembly fixture (outsourcing)	1	500	500	15	15
28	BQ1023-03-041	Cooler lower beam right stiffener assembly fixture (outsourcing)	1	500	500	15	15
29	BQ1023-03-042	te assembly fixture	1	3300	3300	100	100
30	BQ1023-03-043	Front girth upper beam assembly fixture	1	3300	3300	100	100
31	BQ1023-03-044	Front wall upper beam inner plate assembly (+ homemade)	1	3000	3000	90	90
32	BQ1023-03-037	Car top front beam assembly fixture	1	1650	1650	50	50
33	BQ1023-03-046	Car top assembly fixture	1	4000	4000	120	120
34	BQ1023-03-047	Rear coaming assembly fixture	1	3000	3000	90	90
35	BQ1023-03-049	Cover assembly (single row)	1	12500	12500	382	382
36	BQ1023-03-050	Rear coaming assembly (single row)	1	16000	16000	474	474
37	BQ1023-03-063	Upper inner plate assembly, left C pillar	1	6600	6600	200	200
38	BQ1023-03-064	Inner plate assembly on right C-pillar	1	6600	6600	200	200
39	BQ1023-03-065	Right A-pillar inner plate assembly fixture	1	10000	10000	300	300
40	BQ1023-03-066	Left A-pillar inner plate assembly fixture	1	10000	10000	300	300
41	BQ1023-03-067	Right A-pillar outer plate strengthens plate assembly	1	9200	9200	280	280
42	BQ1023-03-068	Left A-pillar outer plate strengthens plate assembly	1	9200	9200	280	280
43	BQ1023-03-069	Right B-pillar outer plate strengthens plate assembly	1	6600	6600	200	200
44	BQ1023-03-070	Left B pillar outer plate reinforcement plate assembly	1	6600	6600	200	200
45	BQ1023-03-071	Right B pillar and upper inner plate assembly	1	3300	3300	100	100
46	BQ1023-03-072	Left B pillar and upper inner plate assembly	1	3300	3300	100	100
47	BQ1023-03-073	C pillar assembly, right side	1	12500	12500	370	370

48	BQ1023-03-074	Left C pillar assy	1	12500	12500	370	370
49	BQ1023-03-075	Right side girth assembly 1 station	1	128000	128000	3890	3890
50	BQ1023-03-076	Left side girth assembly 1 station	1	128000	128000	3890	3890
51	BQ1023-03-077	Right side girth assembly 2 stations	1	115000	115000	3500	3500
52	BQ1023-03-078	Left side girth assembly 2 stations	1	115000	115000	3500	3500
53	BQ1023-03-079	Right side girth assembly 3 station	1	115000	115000	3500	3500
54	BQ1023-03-080	Left side girth assembly 3 station	1	115000	115000	3500	3500
55	BQ1023-03-081	Right side circumference assembly 4 stations	1	96000	96000	2900	2900
56	BQ1023-03-082	Left side girth assembly 4 stations	1	96000	96000	2900	2900
57	BQ1023-03-085	Left B-pillar inner plate assembly (single row)	1	9800	9800	299	299
58	BQ1023-03-086	Right B-pillar inner plate assembly (single row)	1	9800	9800	299	299
59	BQ1023-03-087	Left side enclosure assembly fixture (single row)	1	23000	23000	700	700
60	BQ1023-03-088	Right side enclosure assembly fixture (single row)	1	23000	23000	700	700
61	BQ1023-03-089	Left side enclosure assembly fixture (single row)	1	23000	23000	700	700
62	BQ1023-03-090	Right side enclosure assembly fixture (single row)	1	23000	23000	700	700
63	BQ1023-03-092	Left lower beam nut plate fixture	1	4300	4300	130	130
64	BQ1023-03-093	Right lower beam nut plate fixture	1	4300	4300	130	130
65	BQ1023-03-182	Side girth bottom beam outer plate punching fixture	1	2300	2300	70	70
66	BQ1023-03-096	Reinforcing plate assembly on left C-pillar	1	1650	1650	50	50
67	BQ1023-03-097	Reinforcing plate assembly on right C-pillar	1	1650	1650	50	50
68	BQ1023-03-098	Left rear door inner panel sub assembly fixture	1	13000	13000	400	400
69	BQ1023-03-099	Right rear door inner panel sub assembly fixture	1	13000	13000	400	400
70	BQ1023-03-100	Left rear door inner panel assembly fixture	1	13000	13000	400	400
71	BQ1023-03-101	Right rear door inner panel assembly fixture	1	13000	13000	400	400
72	BQ1023-03-102	Left rear door crash rod assembly fixture	1	3300	3300	100	100
73	BQ1023-03-103	Right rear door crash rod assembly fixture	1	3300	3300	100	100
74	BQ1023-03-104	Left and right front door sealing rubber strip clamping fixture	1	23000	23000	700	700
75	BQ1023-03-105	Left and right rear door sealing rubber strip clamping fixture	1	23000	23000	700	700
76	BQ1023-03-106	re	1	21000	21000	640	640
77	BQ1023-03-107	Hood latch welded assembly	1	1300	1300	40	40
78	BQ1023-03-108	Hood front stiffener assembly	1	4600	4600	140	140
79	BQ1023-03-109	Repair frame for left/right rear door inner panel	1	5000	5000	150	150
80	BQ1023-03-110	Right front door inner panel assembly fixture	1	18200	18200	550	550
81	BQ1023-03-111	Left front door inner panel assembly fixture	1	18200	18200	550	550
82	BQ1023-03-112	Right front door inner panel assembly fixture	1	18200	18200	550	550
83	BQ1023-03-113	Left front door inner panel assembly fixture	1	18200	18200	550	550
84	BQ1023-03-114	Right front door crash rod assembly fixture	1	4000	4000	120	120
85	BQ1023-03-115	Left front door crash rod assembly fixture	1	4000	4000	120	120
86	BQ1023-03-116	Right front door hinge reinforcing plate assembly fixyure	1	3300	3300	100	100
87	BQ1023-03-117	Left front door hinge reinforcing plate assembly fixture	1	3300	3300	100	100
88	BQ1023-03-118	Right rear side door hinge reinforcing plate assembly fixture	1	2650	2650	80	80
89	BQ1023-03-119	Left rear side door hinge reinforcing plate assembly fixture	1	2650.04	2650.04	80	80
90	BQ1023-03-120	Left/right rear door panel assembly fixture	1	30000	30000	900	900
91	BQ1023-03-121	Left/right front door panel assy	1	30000	30000	900	900
92	BQ1023-03-122	G3 Left and right sub-board assembly	1	16500	16500	500	500
93	BQ1023-03-123	Front bar mounting bracket welding fixture	1	6600	6600	200	200
94	BQ1023-03-124	TUV left and right sub-board assembly	1	13200	13200	400	400
95	SC019	Radiator mounting bracket left welding fixture	1	50	50	1.5	1.5
96	SC020	Radiator mounting bracket right welding fixture	1	50	50	1.5	1.5

97	XZSC002	Horn mounting bracket left/right positioning welding fixture	2	25	50	1.5	1.5
98	XZSC003	Heat sink upper beam horn mounting point punch fixture	1	7	7	0.2	0.2
99	XZSC004	Heat sink upper beam stiffener horn mounting point drilling fixture	1	7	7	0.2	0.2
100	XZSC005	Bolt positioning fixture for heat insulation installation of front coaming exhaust pipe	1	16	16	0.5	0.5
101	SC012	Drilling fixture for mounting holes on the left front door rubber strip	1	16	16	0.5	0.5
102	SC013	Drilling fixture for mounting holes on the right front door rubber strip	1	16	16	0.5	0.5
103	SC014	Water cut mounting hole on the left rear door drilling fixture	1	16	16	0.5	0.5
104	SC015	Right rear door water cut mounting hole drilling fixture	1	16	16	0.5	0.5
105	SC016	Left front door upholstery bracket welding fixture	1	50	50	1.5	1.5
106	SC017	Right front door interior trim bracket welding fixture	1	50	50	1.5	1.5
107	SC044	Door rail left/right positioning fixture	1	33	33	1	1
108	SC021	Cargo side panel back support tooling left	1	7	7	0.2	0.2
109	SC051	Cargo side panel back support tooling right	1	7	7	0.2	0.2
110	SC022	Cargo side panel back support tooling left	1	7	7	0.2	0.2
111	SC052	Side plate rear support tooling right	1	7	7	0.2	0.2
112	SC023	Cargo side plate front end positioning fixture	1	50	50	1.5	1.5
113	SC007	Rear floor seat latch assembly positioning tool	1	50	50	1.5	1.5
114	SC024	Seat nut plate positioning tool	2	25	50	1.5	1.5
115	SC025	ECM support tooling	1	33	33	1	1
116	SC047	Air conditioning after the left/right support fixture	2	25	50	1.5	1.5
117	SC049	Central storage box holder fixture	1	66	66	2	2
118	XZSC006	BCM support positioning welding fixture (New Iranian project)	1	33	33	1	1
119	XZSC007	Bolt positioning tool for front floor exhaust pipe heat insulation installation	1	33	33	1	1
120	XZSC008	Roof cover front beam punch kit (add antenna amplifier holes)	1	16	16	0.5	0.5
121	BQ1023-03-127	Floor left beam assembly fixture	1	4000	4000	120	120
122	BQ1023-03-128	Floor right beam assembly fixture	1	4000	4000	150	150
123	BQ1023-03-129	Right C-pillar lower inner plate assembly fixture	1	3300	3300	100	100
124	BQ1023-03-130	Front floor assembly one station fixture	1	13250	13250	400	400
125	BQ1023-03-131	Front floor assembly one station repair welding fixture	1	1650	1650	50	50
126	BQ1023-03-132	Front floor assembly 2-station fixture	1	16000	16000	480	480
127	BQ1023-03-133	Middle floor first beam fixture	1	7600	7600	230	230
128	BQ1023-03-134	Middle floor middle beam assembly fixture	1	3000	3000	90	90
129	BQ1023-03-135	Middle floor rear beam fixture	1	3400	3400	105	105
130	BQ1023-03-136	Back floor assembly one station pre-welding fixture	1	1650	1650	50	50
131	BQ1023-03-137	Rear floor assembly a station fixture	1	15000	15000	420	420
132	BQ1023-03-138	Back floor assembly one station repair welding fixture	1	1500	1500	40	40
133	BQ1023-03-139	Rear floor assembly 2-station fixture	1	13500	13500	410	410
134	BQ1023-03-140	Front center floor assembly fixture	1	7000	7000	200	200
135	BQ1023-03-141	Front center floor assembly repair welding fixture	1	4000	4000	120	120
136	BQ1023-03-142	Cargo box corner Assembly left fixture (TUV)	1	6000	6000	180	180
137	BQ1023-03-143	Cargo box corner assembly right clamp (TUV)	1	6000	6000	180	180
138	BQ1023-03-144	Cargo box corner Assembly Left fixture (G3)	1	2000	2000	60	60
139	BQ1023-03-145		1	2000	2000	60	60
140	BQ1023-03-146	fixture for front panel assembly of cargo box	1	6000	6000	180	180
141	BQ1023-03-175	Clamp for the third beam assembly of the floor of the cargo box (CO2 welding)	1	2000	2000	60	60
142	BQ1023-03-147	Cargo box bottom beam five-assembly fixture	1	2300	2300	70	70
143	BQ1023-03-157	Cargo box plate assembly left fixture (single row)	1	13200	13200	400	400
144	BQ1023-03-153	Cargo box inner plate assembly left fixture	1	7000	7000	210	210
145	BQ1023-03-158	Cargo box inner panel assembly right fixture (single row)	1	14000	14000	400	400

146	BQ1023-03-154	Cargo box inner panel assembly right fixture(TUV)	1	7000	7000	210	210
147	BQ1023-03-150	cargo box left panel assembly fixture	1	12000	12000	360	360
148	BQ1023-03-159	cargo box left panel assembly fixture (single row)	1	23000	23000	700	700
149	BQ1023-03-151	Cargo box right panel assembly fixture	1	12000	12000	360	360
150	BQ1023-03-160	cargo box right panel assembly fixture (single row)	1	23000	23000	700	700
151	BQ1023-03-152	Cargo box bottom assembly fixture	1	40000	40000	1200	1200
152	BQ1023-03-161	Cargo box bottom assembly fixture(single row)	1	28538	28538	865	865
153	BQ1023-03-162	Clamp for rear coaming assembly of cargo box	1	4500	4500	130	130
154	BQ1023-03-163	Cargo box assembly fixture	1	56000	56000	1700	1700
155	BQ1023-03-164	Side Wall reinforcement beam fixture (TUV)	1	6600	6600	200	200
156	BQ1023-03-165	Cargo box assembly repair welding fixture 1	1	4600	4600	140	140
157	BQ1023-03-166	Cargo box assembly repair welding fixture 2	1	4600	4600	140	140
158	BQ1023-03-167	Cargo box assembly turning fixture	1	30000	30000	900	900
159	BQ1023-03-176	Front panel on bezel	1	1800	1800	50	50
160	BQ1023-03-177	Cargo box side board back support	1	2300	2300	70	70
161	SC057	Floor assembly welding tooling	1	39.85	39.85	1.2	1.2
TOTAL			164		1999999.89	60568.9	60568.9

