


6 Axis Articulated Arc Welding Robots

TAWERS Series

January 2018





Robot Systems with Integrated Welding Power Source Technology



Torch type selectable to fit your application!

WGII/WGHII



Separate Type



Through-Arm Type



External Type

Superior wire feedability and reduced cable interference

interference

Focused on reducing cable Focused on wire feedability





■Manipulator Lineup (as of January 2018)

	TS series		TM series				TL series		
	800	950	1100	1400	1600	1800	2000	1800	2000
Separate	_	_	0	0	0	0	0	_	- 17-
Through-Arm	0	0	0	0	0	0	0	225)	8_0
External	0	0	0	0	-	(-	1 - 2	0	0
Payload	8	kg	6	kg	4 kg	6	kg	8 kg	6 kg

Rated Welding Output:

WGIII: 350 A @ 80 % duty cycle (CV). 350 A @ 60 % duty cycle (pulse).

WGHII: 450 A @ 100 % duty cycle (CV/pulse)

A variety of features specialized for arc welding

Feature (TW/TL) Enhanced Basic Performance

Increased Motion Speed

TM-1400: Speed of main 3 axes increased by 22 % on average. (approx. 42 /s more than TA type)

Extended Reach

TM-1400: 1 437 mm (63 mm more than TA type)



makes arm compact and improves accessibility to workpieces.







In addition to Through-Arm Type and External Type,

A third choice—Separate Type (TM series)

Revolutionary new type of arc welding robot with advantages of both Through-Arm Type and External Type.

High Wire Feedability Less Gable Interference







New type welding robot achieves even higher quality welds.



Robot Systems with **Integrated Welding Power Source Technology**

"Weld Navigation" allows easy parameter setting (Standard)

Weld Navigation


Easy setting with Teach Pendant



Rich welding parameter database developed through our long experience

without notice.

"Weld Navigation" reduces parameter setting time.



Two Easy Steps:


 Select weld joint. The figure changes according to the joint.



Select plate thicknesses. That's all!

The right parameters automatically

Leg length and weld speed are also adjustable.



Weld Navigation recalculates weld current and voltage according to the changes.

Notes: *Parameters by Weld Navigation are guideline only and do not guarantee welding result. Consult us for material and processes available with Weld Navigation.

WGII controller with high performance


 Compared to the conventional model, 6 times faster main CPU and 4 times more memory capacity reduce start-up time by 50 % to about 30 seconds.






Improved maintainability

- Swivel rack in the case makes maintenance easy and saves space.
- Cables with connectors on both ends reduce Cable exchange time.








Cables with connectors on both ends




TAWERS Technology— Various Welding Processes

- SP-MAGI for short-circuit mixed gas welding on thin plates
- HD-Pulse for high-speed and low-spatter in high-current pulsed mixed gas welding
- ·MTS-CO2 for CO2 welding

TAWERS Welding Process Guide





<u>APPLICATIONS</u>

Super Active TAWERS

Super Active Wire Feed Process

Achieves even lower spatter with high-precision control of wire feed speed.

Super Active MAG Super Active CO₂



See the page of "Super Active TAWERS" for details.



TAWERS Technology— Various Welding Processes

- SP-MAGII for short-circuit mixed gas welding on thin plates
- MTS-CO2 for CO2 welding


(Super-imposition Control)


Greatly reduces spatter in mixed gas (MAG) welding on thin plates

Welding waveform control achieves low spatter in short-circuit transfer range.


Spatter comparison (1 minute at 200 A)







Recommended Panasonic wire YM-50MT used.



Detects initial short-circuit and then the secondary switching* circuit reduces weld current rapidly to prevent micro-short circuit that causes spatter.

 Neck control
 Detects a neck of the droplet and then the secondary switching* circuit
 reduces weld current rapidly to prevent fuse effect that causes spatter.

s weld pool oscillation and prevents micro-short circuit that causes spatter.


Superimposes the current immediately after a short-circuit release and allows for higher wire-melting speed. This makes the next short circuit smooth and also makes the short-circuit cycle shorter.

*Secondary switching is the spatter reduction process that rapidly reduces weld current immediately before and after shot-circuit and allows for smooth transitions


(Metal Transfer Stabilization Control)

Reduces spatter by up to 75 % using inexpensive CO2 gas

MTS control added to SP-MAG technology reduces spatter of CO2 welding.




CO2 welding delivers uniform pan-bottom shaped penetration.



· Joint: Fillet · Base metal: 2.3 mm mild steel SPCC · Weld current: 120 A Weld speed: 0.3 m/min • Wire: YGW12 (1.2 mm) • Shielding gas: COz







TAWERS Technology— Various Welding Processes

- Normal pulse for ultra-low spatter welding
- ·HD-Pulse for high-speed and low-spatter welding

HID-Pulse

(Hyper Dip-Pulse Control)


Achieves high-speed pulsed welding

Short and narrow arc prevents undercuts during high-speed welding.

■HD-Pulse advantages:


- Preventing undercuts during high speed welding.
- Dip (Short circuit) transfer enabling lower heat input with better gap handling capability.
- Precisely controlled dip timing reducing spatter.


■High speed welding



Preventing undercuts with ideal penetration!

■Type of the droplet transfer





■Spray transfer range: 280 A or more

Weld process	SP-MAG II	Normal-Pulse	HD-Pulse
Weld speed	good	good	excellent
Spatter	good-fair	excellent	good
Penetration pattern	fair	good-fair	excellent
Undercut	fair	fair	excellent
Heat input	fair	fair	good
Gap handling	fair	fair	good
Overall	fair	fair	excellent

- SP-MAG II disadvantage:
 Spatter in high-current range.
- Normal-pulse disadvantage: Undercuts in high-speed welding.



HD-Pulse process is ideal for high-current and high-speed welding.



Standard Features

External Communication (Ethernet)


Production and Quality Control on LAN

The LAN connection allows you to share welding data with other robots and improve production and quality control.



Flying Start

Executes arc-on/off programs a little before the torch reaches the weld start/end point to reduce cycle times.



Wire Auto Retract

Wire feed start


As the robot moves to weld start points, the wire is retracted automatically; thereby, improving arc start.

Weld start point Arc start



Wire Stick Auto Release (for CO₂/MAG)

Automatically detects a wire stuck at the end of a weld and re-ignites the arc to release the wire.



Pitch Movement ("Jog settings")

This function enables robot movement at a pre-set

distance by every click of the jog dial. This is useful when working in narrow, constricted spaces or in fine-tuning robot position.




Lift Start / Lift End

Quality Weld Starts and Ends. Spatter and Cycle Time Reduction.

The robot lifts up the welding torch quickly at the start and end of the weld. By coordinating the robot motion with the welding waveform and wire feed control, quality and cycle time are improved.

(Much quicker than wire retraction.)



Arc Start Retry (for CO₂/MAG)

Detecting a failure of arc start, the robot automatically starts arc ignition again.



Torch Angle Display (Teach Pendant)

Torch angle is displayed on the screen, making it possible to reduce teaching time and obtain consistent bead appearance.




Program Test

In Teach mode, operator can safely verify taught program including welding without switching to Auto mode.





Optional Features




More advanced welding system available Utilize features such as external communication and large capacity memory.

Optional Software Auto Extension Control

Compensates heat distortion or teaching error of odd-shaped work.

Robots detects changes in wire extension and compensates automatically.



Cooperative Multi-Robot Control

Allows cooperative control between two robots.

Synchronous Weaving Low Pulse (Spiral Weaving Included) [Spiral weaving movement] ·Synchronizes weld current, Torch movement wire feed speed and weaving completely. Condition A ·Alternates condition A/B Condition B during weaving, which is ideal for welding of different ·Weld current thickness plates. (One for thin plate, the other for thick Condition plate) ·Wire feed speed

Small Type Arc Welding Robots

TS Series



Succeed TAWERS' welding performance

Various welding styles

Super Active TAWERS / TAWERS-TIG / TAWERS or others

[TW axis: Hollow arm]

Torch type selectable between through-arm



Improve small work productivity

Space saving

48 % smaller footprint

(example of one customer, compared with our TM-1100)

Floor/Wall/Ceiling mount

(Ceiling mount type is special specification.)

High speed despite 8 kg payload Maximum motion speed: 540°/s (average for all axes)


Dimensions & Work Envelope

For working envelope of point O, consult us.

Short Type
TS-800

Short Type
TS-950

(Unit: mm)



Manipulator General Specifications

4×914


Model		TS-800	TS-950	
Туре		Short arm	Short ar	
Structur	re	6 axis articulated		
Payload		8 kg		
Maximu	m Reach	841 mm	971 mm	
Minimu	m Reach	159 mm	190 mm	
Working	g Range	682 mm	781 mm	
	RT (Rotating Trunk)	326°/s		
	UA (Upper Arm)	326°/s		
Max. Motion	FA (Forearm)	510°/s		
Speed	RW (Rotating Wrist)	518°/s		
	BW (Bending Wrist)	518°/s		
	TW (Twisting Wrist)	1 040°/s		
Position Repeatability		±0.05 mm		
	Total Power	2 100 W		
Motors	Brakes	All axes		
Mounting		Floor/Ceiling*1/Wall*2		
Weight		55 kg 56 kg		


^{*1:} Ceiling mount type is factory optional.

^{*2: *}Setting by service personnel is necessary. *Working range of RT axis is limited.


Dimensions & Work Envelope





























Middle Type TM-1600









Long Type TM-1800








Manipulator General Specifications

Model		TM-1100	TM-1400	TM-1600	TM-1800	TM-2000	TL-1800	TL-2000		
Type		Short arm	Standard arm	Middle arm	Long arm	Long arm	Long arm	Long arm		
Structure		6 axis articulated								
Payload		6 kg		4 kg	6 kg		8 kg	6 kg		
Maximum Reach		1 163 mm	1 437 mm	1 639 mm	1 809 mm	2 011 mm	1 801 mm	1 999 mm		
Minimum Reach		418 mm	404 mm	513 mm	430 mm	550 mm	383 mm	491 mm		
Working Range		745 mm	1 033 mm	1 126 mm	1 379 mm	1 461 mm	1 418 mm	1 508 mm		
Max. Motion Speed	RT (Rotating trunk)	22575		210%	1957s		1957s			
	UA (Upper arm)	2257s		210%	1977s		197/s			
	FA (Forearm)	225%s		2157/s	205%s		2057s			
	RW (Rotating wrist)	425%s		425%s	425%s		385%s			
	BW (Bending wrist)	425%s		4257/s	425%s		3757s			
	TW (Twisting wrist)	6297s		6297s	629%s		62475			
Position Repeatability		±0.08 mm			- 9	±0.10 mm	±0.08 mm	±0.15 mm		
	Total Power	3 400 W 4 700 W				5 050 W				
Motors	Brakes	All axes								
Mounti	ng		0		Floor / Ceiling*		20 20			
Weight		156 kg	170 kg	180 kg	215 kg	217 kg	215 kg	216 kg		

Dimensions & Work Envelope







■Controller / Welder Technical Specifications


Model	WGIII	WGHII				
Dimensions*	W 553 mm x D 550 mm x H 1181 mm	W 553 mm x D 550 mm x H 1407 mm				
Weight**	135 kg	171 kg				
Memory Capacity	acity 40 000 points					
Position Control	Software servo control					
External Memory	Teach Pendant: one SD memory card slot, two USB 2.0 ports (USB 2.0. Hi-Speed not supported)					
Control Axes	6 axes simultaneously (Max. 27 axes)					
Input and Output	Input: 40 points (Optionally expandable up to 2048 points) Output: 40 points (Optionally expandable up to 2048 points)					
Input Power	3 phase, 200 V AC±20 V AC, 22 kVA, 50/60 Hz	3 phase, 200 V AC±20 V AC, 30.5 kVA, 50/60 Hz				
	50/60 Hz (Max. current at servo on: 246 A/5.6 ms)					
Welding Process	COz / MAG / Stainless steel MIG /	Pulse MAG / Stainless pulse MIG				
Output Current Range	30 to 350 A DC	30 to 450 A DC				
Output Voltage Range	12 to 36 V DC	12 to 42 V DC				
Duty Cycle	CV: 80 % @ 350 A Pulse: 60 % @ 350 A	100 %				

Controller (with power unit)




■Teach Pendant





^{17 *}Protruding portions not included. **Teach pendant and connection cable not included.

Note: For details on the power connection, refer to *Connecting primary power source* in the arc welding robot controller manual.



Large Robot Series (GII Controller)

Great material handling capability!

Coordinated multi-robot movement for flexible system without jig.



YS-080GII

HS-220GII

Coordinated movement with WGII/GII robot(s)



Allows to build flexible system without jig.

Maximum configuration: ·Arc welding robot x 2 ·Large robot x 1

GII controller for large robots

Same operation, maintenance and options as conventional robots

■Manipulator General Specifications

Model			YS-080GⅢ	HS-220GⅢ	
Type			6 axis articulated robot		
Payload			80 kg	220 kg	
	RT (Rotating trunk) UA (Upper arm)		±180 °	±178 °	
Working Range			-80 °~ +155 °	-65 "~ +80 °	
	FA (Forearm)	Referenced from Horizontal	-140 "~ +230 "	-130 "~ +230 "	
		Referenced from upper arm	-80 ° +180 °	-73° ~ +190°	
	RW (Rotating wrist)		±360 °	±360 "	
	BW (Bending wrist)		±125°	±128 "	
	TW (Twisting wrist)		±360°	±360 °	
Max. Motion Speed	RT (Rotating trunk)		1707s	120%s	
	UA (Upper arm)		140%	1057s	
	FA (Forearm)		1607s	1107s	
	RW (Rotating wrist)		2307s	1457s	
		ling wrist)	2307s	1457s	
	TW (Twisting wrist)		350%s	220%s	
Position Repeatability		±0.15 mm			
Weight			645 kg	955 kg	